



Worldwide repairs carried out with PolymerMetal®

REP-# 043



In a transformer station plant oil leakages at welding seams of a conservator were repaired with the direct-MM-bonding method by using MM-metal oL-steelceramic, Hardener red and Hardener yellow.

MultiMetal
the MetalExistenceCompany®