



Worldwide repairs carried out with PolymerMetal®

REP-# 090



A cover with Ceramium was reconstructed. The coating was affected in two working procedures: First a surface reconstruction with Ceramium, pasty and Hardener CE. Second an application with Ceramium, liquid with Hardener CE.

MultiMetall
the MetalExistenceCompany®