



Worldwide repairs carried out with PolymerMetal®

REP-# 108



Repair of worn piston rods caused by the exhausts of a blast furnace. The piston rods were brought to nominal diameter again using Ceramium. After the repair has been completed the piston rods are in operation again over 3 years.

MultiMetal
the MetalExistenceCompany®