




Worldwide repairs carried out with PolymerMetal®

REP-# 060



A tanker (size 15.000 GRT) loaded with petrol, touched ground. Damage was an extensive leakage with a size of 200 mm x 700 mm. The repair was carried out under water using MM-metal UW with Hardener UW9 and a metal plate.

MultiMetall
the MetalExistenceCompany®