





*Worldwide repairs carried out with PolymerMetal<sup>®</sup>*

REP-# 064



A crack at an enamel coated chemical plant for the production of solvents was filled with Ceramium and Hardener CE.

**MultiMetall**  
the MetalExistenceCompany<sup>®</sup>